Oct. 20, 2016

DOT/EPA/DEEP 195 Stratford/Raymark Waste

- 1. Project & investigation description, findings thus far
- 2. Future work delineation requirements
 - Is QAPP required? Tier 3 data validation? Can we use Sikorsky QAPP and just modify as needed (i.e. personnel changes)? Does QAPP need to be approved before delineation work starts?

,405

- Sample intervals where material is deep is there a need to sample all surficial intervals?
- Grid spacing
- If RMW extends under I95
- Geotech borings
- 3. Project construction/removal work
 - Feasibility of EPA performing work
 - DOT contractor performs work
 - i. MOA/CO needed?
 - ii. Work plan needed?
 - iii. Contractor approval by EPA?
- 4. Use of 4' of clean fill & warning layer for deep material
 - Is an O&M plan required?
 - Inspections?

